

ERCA Safety Commission - Safety Alert 2/2008

The aim of releasing ERCA safety alerts is to disseminate up to date information which will help to avoid accidents on ropes courses. We are committed to providing unbiased information about the sequence of events and the causes of accidents. We are neither in the position to, nor do we have the intention of, undertaking in-depth on-the-spot investigations. Please send your comments and questions regarding the safety alert to sicherheit@erca.cc

2/2008 Recall and Replacement of Edelweiss Shock Absorbers (Deutsche Version auf Seite 2)

We have received a recall for shock absorbers by Edelweiss in german language. Please find the translation below. Edelweiss wrote:

“Recall and Replacement of EDELWEISS Shock Absorbers

Affected Products: Delivery Period 2007 with the following serial numbers

23.1J10V06, 31.6J02V07, 31.5J05V07, 31.3J08V07, 30.8J11V07, 32.3J07V07
31.9J02V07, 31.0J12V07, 23.0J11V06, 32.6J02V07, 31.9J06V07

Edelweiss Ltd has announced that during a routine internal safety inspection a number of samples of the Edelweiss Shock Absorbers were found to fail below the required level of 900daN¹ of the Y-Lanyard. In line with our safety and product liability guidelines this situation requires a rigorous response: we are asking all customers to immediately stop using any shock absorbers with the serial numbers listed above.

The Use of these Shock Absorbers could be Dangerous!

For a replacement, please contact your dealership or return your product to our agencies:

Agency Contact Details

Austria: Mountain Sports GmbH, Moosfeldstr.1, A-5101 Bergheim, Austria

Germany: Get Gear, Andreas-Kasperbauer-Str. 10a, D-85540 Haar, Germany

As compensation for your postage and packaging costs we will send a free copy of a technical guide about rope usage.”

¹ Note: 900daN = 9 kN

Warnhinweis der ERCA-Sicherheitskommission 2/2008

Warnhinweise der ERCA werden mit dem Ziel der Unfallprävention zeitnah an alle Mitglieder versendet. Wir bemühen uns um eine sachliche Darstellung der Vorgänge und Ursachen ohne eine genaue Untersuchung des Vorfalls vor Ort vornehmen zu können oder zu wollen. Bitte senden Sie Ihre Anregungen und Fragen zu diesem Thema an:

sicherheit@erca.cc

2/2008 Rückhol- und Umtauschaktion für Edelweiss Shock Absorber

Wir haben folgende Mitteilung von Edelweiss erhalten und möchten unseren Mitgliedern diese Information hiermit weitergeben. Edelweiss schreibt:

„Rückhol- und Umtauschaktion für EDELWEISS Shock Absorber

Lieferzeit 2007 mit folgenden Seriennummern:

23.1J10V06, 31.6J02V07, 31.5J05V07, 31.3J08V07, 30.8J11V07, 32.3J07V07
31.9J02V07, 31.0J12V07, 23.0J11V06, 32.6J02V07, 31.9J06V07

Die Firma Edelweiss gibt bekannt, dass anlässlich einer hauseigenen Durchführung von Stichproben, Leistungswerte unter 900daN der Y-Lanyard der oben genannten Shockabsorber gefunden wurden. Unsere Richtlinien für Produkthaftung und Sicherheit verlangen in einem solchen Fall eine kompromisslose Vorgangsweise : Daher bitten wir Sie, die Shockabsorber mit oberen Seriennummern nicht mehr zu verwenden.

Der Gebrauch könnte gefährlich sein!

Den Umtausch können Sie über Ihren Fachhändler oder auch direkt mit der Post an unsere Agentur vornehmen :

Österreich : Mountain Sports GmbH, Moosfeldstr.1, A-5101 Bergheim

Deutschland: Get Gear, Andreas-Kasperbauer-Str. 10a, D-85540 Haar

Als Ersatz für Porto- und Verpackungsspesen erhalten Sie ein Seiltechnik (Lehrbuch) kostenlos.“